

Hanlong Technology CO., LTD.

Firmware Release Notes

Firmware Version 1.0.0.18

Product Name: Unicorn Series Products

Date: August 19, 2009

SUMMARY OF UPDATES

The main purpose of this release is additional features implementing and addressing T.38 issues in previous releases.

CHANGES SINCE FIRMWARE RELEASE 1.0.0.18

BUG FIXES

- Fixed some T.38 issues
- Fixed DNS SRV issue
- Fixed Server domain resolve issue in boot loader
- Fixed sip server setting issue in Unicorn610x

ENHANCEMENTS

- Add configuration option: Allow DHCP Option which can be set to override firmware server
- Add configuration option: Allow DHCP Option 42 to override NTP server
- Add configuration option: Allow DHCP Option 2 to override Time Zone setting
- Add configuration option: DHCP vendor specific information (Option 43)
- Interoperate with BroadSoft softswitch
- Dial plan support such as: {<11=34abc><12=56xyz>[[*x]+}
- Shorten boot-up time
- ATA and Gateway: Report DTMF signal even it is about 50ms
- IP Phone: User can customize "Display Info in LCD"